

Geospatial Modeling & Visualization

A Method Store for Advanced Survey and Modeling Technologies


GMV Geophysics GPS Modeling Digital Photogrammetry 3D Scanning Equipment Data and Projects by Region



Z+F Laser Control: Manually Identifying Feature Points

[MANUALLY IDENTIFYING FEATURE POINTS PT 1](#)

[MANUALLY IDENTIFYING FEATURE POINTS PT 2](#)
[CONTINUE TO...](#)

If the automatic Extract and Identify Feature Points operation did not work or if you need to add additional feature points to a scan to get better results (and less error), then you will need to manually add a few feature points to a scan and its associated images.

1. First, click the Passpair Definition button  on the Color Toolbar. Immediately, you should see all of the points in the 2D View identified from that automatic feature point extraction. If you select an image from the TOC and open it, you will also see feature points in the image. The key to good color mapping is it have feature points in all/most of your images. When you have a scan that is a large %age sky then it can often be difficult for the automatic feature point extraction to execute. Therefore, you will want to place points in areas where you would like to see an improvement of the color mapping (areas that were not mapped well initially) and you also want a good distribution of points across all of your images where points can be easily identified.

2. By default when you open the Passpair Definition options the 2D Zoom Windows will automatically open for the scan in the 2D View and also for an image that you open. To effectively use the 2D zoom window in the 2D View (Gray View) change the Selection Mode from Rectangular to Point by clicking on the button several times until it changes from  to .

Now as you click and drag your mouse around the 2D View the view changes in the 2D View.

3. Now identify some prospective Feature points between a scan and its images. Drag the mouse in the 2D view to identify a Feature point location in the Zoom View – click on the point in the Zoom view and Name it (something that is easy to remember). Now identify the same point in the image view – Click on it (using the Zoom View) and give it the EXACT SAME NAME (copying and pasting the name often works best here). Now, check all of the images to see if the same point is identifiable in any other image, if so select the image, identify the point and give point the SAME NAME.





Figure 5: Process of identifying and naming manually identified points.

4. Rinse and repeat.

5. Once you have identified all of the manual feature points (3-10), click the calculate extrensics button  to calculate the external calibration file.

6. Note the error and Generate Color Scans to view the results. Verify the quality of the results and proceed as necessary.

If you are satisfied with the quality of your results, continue to [Z+F Laser Control: Filtering and Exporting Your Data](#)



You are reading the series: [Z+F Laser Control](#)
[Z+F Laser Control: Color Mapping](#)
Z+F Laser Control: Manually Identifying Feature Points
[Z+F Laser Control: Filtering and Exporting Your Data](#)

Please cite this document as: Green, Vance. 2012. Z+F Laser Control: Manually Identifying Feature Points. CAST Technical Publications Series. Number 7405. <http://gmv.cast.uark.edu/scanning/zf-laser-control-manually-identifying-feature-points-2/>. [Date accessed: 27 April 2013]. [Last Updated: 9 May 2012]. *Disclaimer: All logos and trademarks remain the property of their respective owners.*

Login

[Log in](#)